LOCALITY STORMWATER UTILITY REPORTING FORM

DUE ANNUALLY BY OCTOBER 1

The purpose of this form is to implement the following stormwater utility reporting requirement established by Paragraph H.1. of Item 363 of the FY15-16 State Budget [Chapter 665]: "Each locality establishing a utility or enacting a system of service charges to support a local stormwater management program pursuant to § 15.2-2114, Code of Virginia, shall provide to the Department of Environmental Quality by October 1 of each year, in a format specified by the Department, a report as to each program funded by these fees and the expected nutrient and sediment reductions for each of these programs."

Each Locality subject to the reporting requirement set forth above shall complete and submit this form to the DEQ by each October 1, to: <u>Joan.Salvati@deq.virginia.gov</u>. [APA update: Please submit this report to LocalGovernment@apa.virginia.gov]

SECTION 1 – LOCALITY INFORMATION

Date: May 26, 2017

Locality Name: Town of Bridgewater

Contact Name: Cherie N. Bowen, Treasurer

Contact Address: P. O. Box 72, Bridgewater, VA 22812-0072

Contact Email: cbowen@bridgewater.town

Contact Phone: (540)908-3399

SECTION 2 - STORMWATER UTILITY FEES

For your stormwater utility fees provide the following information from your most recent annual financial statement.

Fund Name: Stormwater Management Fund Fiscal year: 2016 (July 1, 2015-June 30, 2016)

Revenue	Expenditures	Balance
\$71,747.	\$171,900	\$2,185.

SECTION 3 – FUNDED PROGRAMS AND OTHER MAJOR ACTIVITIES

Provide a brief description of each major program funded by the utility fee system and, where applicable, the expected nutrient and sediment reductions for each of these programs.

A. Operations & Maintenance Program

The stormwater utility operations and maintenance program for the Town of Bridgewater includes but is not limited to the following:


- Maintenance of nine public detention ponds or basins (see detail in attached Town of Bridgewater Stormwater Management Facility Tracking and Reporting report.)
- A regular street sweeping rotation which schedules all streets to be swept at least once every two weeks.
- Program training and administration, inspections of facilities, communication with the public concerning the stormwater program.
- Continuation of a nutrient management plan for Oakdale Park and Sandy Bottom Golf Course (See attached chart – Nutrient Management Plants)


B. Capital Improvement Program

There was no capital improvement project designated for Stormwater Utilities in FY 2016.

Stormwater Management Facility Tracking and Reporting

								Impaired water			
Name	Туре	Location	Total Area	Pervious Area	Impervious Area	Online Date	HUC	segments within HUC	Ownership	Maintenance agreement	Inspection
Tunio (.,,,,,		7010171100		personal in ea					ug. coment	
	Temporary	Latitude: 38.373096°									
Garst Property (137-(5)-L4)	Sediment Basin	Longitude: -78.951536°	6.70	5.60	1.10	06/2005	PS23	Cook's Creek	Public		11/11/2015
	Temporary	Latitude:38.374961°									
Garst Property (137-(5)- L1)	Sediment Basin	Longitude: -78.952941°	2.00	2.00	0.00	06/2005	PS23	Cook's Creek	Public		11/11/2015
Oak Meadows	Detention pond	Latitude:38.375699° Longitude:-78.957539°	22.85	16.56	6.29	06/2005	PS25	North River	Public		11/11/2015
	·					·					
		Latitude:38.376861°									
Dinkel Pond	Retention pond	Longitude:-78.963654°	56.70	46.33	10.37	06/2005	PS25	North River	Public		11/11/2015
Bridgewater College	Datastias saud	Latitude:38.376455°	6.25	2.55	2.70	02/2012	DCDE	North Diver	Duitanta	Vaa	11/12/2015
(Stone Village)	Retention pond	Longitude:-78.967384°	0.25	3.55	2.70	03/2013	PS25	North River	Private	Yes	11/12/2015
RMH Rehab Center	Subcurface SWM	Latitude:38.385295°									
(Formerly Backstage Video)	System	Longitude:-78.971942°	0.37	0.13	0.24	06/2005	PS25	North River	Private	Yes	11/12/2015
		Latitude:38.386547°									
Oakdale Park	Detention Pond	Longitude:-78.96529°	76.50	57.36	19.14	06/2005	PS25	North River	Public		11/12/2015
Parkside Village	Detention pond	Latitude:38.388783° Longitude:-78.9647°	26.80	21.30	5.50	03/2012	PS25	North River	Public		11/12/2015
											,,
Bridgewater Retirement		Latitude:38.38465°									
(Maple Terrace)	D-Raintank™	Longitude:-78.970763°	0.21	0.07	0.14	03/2007	PS25	North River	Private	Yes	11/12/2015
MC - de - Mare d	Batantina	Latitude:38.389859°	40.50	7.20	2.42	06/2005	DCGE	No all Birds	D 1-11-		44/42/2045
Windsor West	Detention pond	Longitude:-78.959116°	10.50	7.38	3.12	06/2005	PS25	North River	Public		11/13/2015
		Latituda;29.200042°									
Turner Ashby High School	Detention pond	Latitude:38.398043° Longitude:-78.955527°	32.10	16.30	15.80	06/2005	PS23	Cook's Creek	Public		11/13/2015
	Petentian nond	Latitude:38.400726°	25 10	32.06	2.04	02/2011	pcon	Dry Piver	Public		11/12/2015
Millview Estates	Retention pond	Longitude:-78.972513°	35.10	33.06	2.04	03/2011	PS20	Dry River	Public		11/13/2015





					TOWN	OF BRIDGEW	/ATER						
			MONTHLY	STREET CL	EANING LAN	E MILEAGE T	OTALS (July	y 2015 thru	June 2016	5)			
Day	July	August	September	October	November	December	January	February	March	April	May	June	Total
1										8.25			
2					8.62						4.26		
3	9.71					15.90							
4			13.20			4.86							
5				17.80	7.48					3.44			
6					10.50								
7		6.69				5.92							
8										8.25			
9				15.60									
10		11.60				11.60						11.40	
11			18.30						9.21	6.88			
12													
13	5.16			6.60	10.20						12.60		
14		15.90											
15										8.25			
16	13.20			9.21		13.20							
17		8.34											
18			18.70			19.50			10.30				
19				12.60									
20					22.00						9.51	7.16	
21		9.21				8.54							
22										12.70			
23	0.05			8.49									
24	8.25	10.10	10.70		0.04			16.00	45.00				
25		12.10	18.70		8.04			16.00	15.80				
26	10.10										47.00		
27	10.40	40.40				0.04					17.80		
28		12.40				8.04		11.00	6.06	0.00			
29				46.60				11.00	6.96	9.89			
30	10.10			16.60							10.00	_	
31	18.10	-0.5:	60.55	00.55	00.5:	07		0= 00	45.5=		18.60	45	0-0
Total	64.82	76.24	68.90	86.90	66.84	87.56		27.00	42.27	57.66	62.77	18.56	659.52

Table 1 – Nutrient Management Plans

	<u>Overview</u>		Nutrient Management	Date
Name	Location	Acreage	Plan Required?	Implemented
Bird Sanctuary	Latitude:38.381331° Longitude:-78.980353°	0.75	No	
Bridgeview Park	Latitude:38.382354° Longitude:-78.980348°	2.61	Yes	
Cooks Creek Arboretum	Latitude:38.387272° Longitude:-78.950122°	8.83	Yes	
Edgebriar Park	Latitude:38.379681° Longitude:-78.978889°	0.24	No	
Greenwood Ames Cemetary	Latitude:38.384977° Longitude:-78.975434°	1.60	Yes	
Harrison Park	Latitude:38.386469° Longitude:-78.974002°	15.72	Yes	
Millview Park	Latitude:38.401786° Longitude:-78.972344°	4.73	Yes	
Oakdale Community Park	Latitude:38.387537° Longitude:-78.965918°	36.50	Yes	6/1/2015
Sandy Bottom Park	Latitude:38.369972° Longitude:-78.965907°	15.02	Yes	6/1/2015
Seven Bridges Park	Latitude:38.380195° Longitude:-78.979304°	2.23	Yes	
Warm Springs Turnpike Park	Latitude:38.392144° Longitude:-78.963934°	0.13	No	
Wildwood Park	Latitude:38.385893° Longitude:-78.988819°	12.00	Yes	
Wynant Park	Latitude:38.380463° Longitude:-78.975434°	0.83	No	

Date	Total Acreage Required	Actual Acreage Implemented
June 30, 2015	14.886	51.52
June 30, 2016	39.696	51.52
June 30, 2017	74.43	
June 30, 2018	99.24	
TOTAL Acreage requiring NMP	99.24	